

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/20/2020

Submitted Date:

08/20/2020

Document Number:

699302409**FIELD INSPECTION FORM**Loc ID 318347 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email            | Comment                         |
|--------------|-------|------------------|---------------------------------|
| ,            |       | rwatzman@kpk.com | <a href="#">All Inspections</a> |
| ,            |       | cogcc@kpk.com    | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 241148      | WELL | PR     | 11/02/1976  | OW         | 123-08936 | SIDNEY STREAR 6 | PR          |

**General Comment:**

| Location   |  |        |             |
|--|--|--------|-------------|
| <b>Lease Road:</b>                                     |  |        |             |
| Type   | Access   |        |             |
| comment:   | Weeds overgrown at location entrance                 |        |             |
| Corrective Action                                      | Comply with Rule 603.f                               | Date:  | 09/03/2020  |
| Overall Good: <input type="checkbox"/>                 |  |        |             |
| <b>Signs/Marker:</b>                                   |  |        |             |
| Type   | WELLHEAD   |        |             |
| Comment:   | adaquate   |        |             |
| Corrective Action:                                     |  | Date:  |             |
| Emergency Contact Number:                              |  |        |             |
| Comment:   |  |        |             |
| Corrective Action:                                     |  |        | Date: _____ |
| <b>Good Housekeeping:</b>                              |  |        |             |
| Type   | OTHER  |        |             |
| Comment:   | Stained soil around WH                               |        |             |
| Corrective Action:                                     | Comply with Rule 907.e                               | Date:  | 09/04/2020  |
| Type   | OTHER  |        |             |
| Comment:   | Mechanical issue leaking seals on pump jack gear box |        |             |
| Corrective Action:                                     | Comply with Rule 605.d                               | Date:  | 09/04/2020  |
| Type   | OTHER  |        |             |
| Comment:   | Stained ground at Pump Jack base                     |        |             |
| Corrective Action:                                     | Comply with Rule 1002..(2).D                         | Date:  | 09/04/2020  |
| Overall Good: <input type="checkbox"/>                 |  |        |             |
| <b>Spills:</b>   |  |        |             |
| Type   | Area   | Volume |             |
| In Containment: No                                     |  |        |             |
| Comment:   |  |        |             |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |             |
| <b>Fencing/:</b>                                       |  |        |             |
| Type   | WELLHEAD   |        |             |
| Comment:   | barb wire  |        |             |
| Corrective Action:                                     |  | Date:  |             |
| Type   | OTHER  |        |             |
| Comment:   | meter box and transformer have fabricated steel pipe |        |             |
| Corrective Action:                                     |  | Date:  |             |
| Type   | PUMP JACK  |        |             |
| Comment:   | fabricated steel pipe and angle iron                 |        |             |
| Corrective Action:                                     |  | Date:  |             |

|                           |  |  |                 |
|---------------------------|--|--|-----------------|
| <b>Equipment:</b>         |  |  | corrective date |
| Type: Pump Jack           | # 1  |  |                 |
| Comment:                  |  |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Prime Mover         | # 1  |  |                 |
| Comment:                  | electric motor                             |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Ancillary equipment | # 1  |  |                 |
| Comment:                  | electric panel, transformers and meter box |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Bradenhead          | # 1  |  |                 |
| Comment:                  | appears to be plumbed to surface           |  |                 |
| Corrective Action:        |  |  | Date:           |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**Facility ID: 241148 Type: WELL API Number: 123-08936 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Thursday 8/20/2020 at approximately 1250 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: center;">Sidney Strear #6 at API #05-123-08936 in Weld County Colorado.</p> <p>While there, I observed a well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>907.e housekeeping: Stained soil around WH. CA date 9-4-2020, see photos 2 &amp; 9.</p> <p>603.f housekeeping: Weeds overgrown at location entrance. CA date 9-3-2020 see photo 3.</p> <p>605.d Mechanical issue: Seals leaking on pump jack gear box. CA date 9-4-2020 see photos 6 &amp; 8.</p> <p>1002..(2).D housekeeping: Stained ground at the base of pump jack. CA date 9-4-2020 see photos 5 &amp; 7.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | revasr | 08/20/2020 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402472496    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5229213">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5229213</a> |
| 699302410    | location pics        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5229180">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5229180</a> |