

Inspection Photos

API: 05-071-07960

Operator: PRESCO INC

Inspection Date: 8/25/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 8/25/2020

Inspection Photos



Photo 1. Facing south along the access road. The road was regraded along a portion of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 8/25/2020

Inspection Photos



Photo 2. This runoff ditch was not properly installed. The disturbance along the side of the road will need to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 8/25/2020

Inspection Photos



Photo 3. This is the area which an erosion gully was previously observed at Lat/Long:37.07589,-104.50931. The erosion gully was repaired and filled in however, this area needs to be stabilized. Stormwater is directed toward this area and will cause erosion if not properly stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 8/25/2020

Inspection Photos



Photo 4. There are culverts installed along the road ascending this hillside.



Photo 5. There is no culvert outlet protection installed to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 8/25/2020

Inspection Photos



Photo 6. Facing southeast along the road ascending the hill side. The road was reggraded along a portion of the road. Additional rock check dams are needed along the side of the road to dissipate stormwater flow and prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 8/25/2020

Inspection Photos



Photo 7. The rock check dams are not properly installed along the road side. Additional rock is needed and the check dams need to extend from side to side with the low point at the center of the check dam.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 8/25/2020

Inspection Photos



Photo 8. Facing toward the culvert inlet installed along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 8/25/2020

Inspection Photos



Photo 9. Facing southwest back down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 8/25/2020

Inspection Photos



Photo 10. Facing east along the road. This area of the road was regraded however, a berm was left on the road which will interfere with stormwater flow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 8/25/2020

Inspection Photos



Photo 11. Facing southeast toward the location. The road continues past the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 8/25/2020

Inspection Photos



Photo 12. Facing southeast toward the location. A shallow pit remains per approved variance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 8/25/2020