

ARGENTA 34-10 31-1

Corrective Actions Taken on the ARGENTA 34-10 31-1 for the COGCC
INC.

Reset cement BMP at the entrance to the reclaimed well pad. The BMP was not correctly installed originally.



Removed all perimeter wattles on the reclaimed access road and well pad.





Removed, bagged, and disposed of the flowering Musk Thistles within the project area.



