

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/16/2020

Submitted Date:

08/28/2020

Document Number:

688800766

FIELD INSPECTION FORM

Loc ID 306806 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 5
Name of Operator: COLORADO OIL & GAS CONSERVATION COMMISSION
Address: 1120 LINCOLN ST SUITE 801
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267716	WELL	AC	02/14/2003	OBW	067-08805	MONITOR WELL 35-6-13-1	EI

General Comment:

On June 16, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Monitor Well 35-6-13 #1 (Shamrock Mine). For the most recent field inspection report of this facility, please refer to document #688800625. The purpose of this site visit was to replace the desiccants within the equipment enclosures, ensure that all equipment on site was secure, and check for leaks at the well heads.

Location

Lease Road:			
Type	Access		
comment:	Locked Forest Service gate on access road. Two track dirt road leads to location.		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to protective steel cage surrounding well head.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Sign mounted to protective steel cage surrounding well head.		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Locked 4' x 4' x 4' expanded metal and angle iron protective cage surrounding well head.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	In-Situ Troll Net Hub with 2 pressure transducers deployed in monitor well.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment. Fiberglass corrugated roof panel on steel equipment shack needs to be replaced.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 267716 Type: WELL API Number: 067-08805 Status: AC Insp. Status: EI**COGCC Comments**

Comment	User	Date
<p>On June 16, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Monitor Well 35-6-13 #1 (Shamrock Mine). For the most recent field inspection report of this facility, please refer to document #688800625. The purpose of this site visit was to replace the desiccants within the equipment enclosures, ensure that all equipment on site was secure, and check for leaks at the well heads.</p> <p>During this inspection 8 desiccant packs and one Desi-Tube were replaced. The desiccants within the equipment enclosures were last replaced on 8/30/19.</p> <p>The battery terminals were free of corrosion.</p> <p>No leaks were observed during this inspection.</p> <p>The corrugated fiberglass roof panel on the equipment shack needs to be replaced.</p>	hughesjo	08/28/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800767	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234585