

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/23/2020

Submitted Date:

08/28/2020

Document Number:

694600085**FIELD INSPECTION FORM**Loc ID 385368 Inspector Name: Duran, Alicia On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 5Name of Operator: COLORADO OIL & GAS CONSERVATION COMMISSIONAddress: 1120 LINCOLN ST SUITE 801City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chollett, Shannon		shannon.chollett@state.co.us	
Andrews, Dave		david.andrews@state.co.us	
Burger, Craig		craig.burger@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214135	WELL	PA	06/16/1984	DA	067-05448	TOUCHSTONE-WEBER HEIRS (OWP) 1	PA

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 214135 Type: WELL API Number: 067-05448 Status: PA Insp. Status: PA

**Workover**

Comment: Borderline Inc. Rig #19  
 7/20/20  
 7:00 AM- Rigged up  
 9:00 AM- Bradenhead gauge read 20 psi. Bled off in 40 secs  
 9:15 AM- Waiting on drill bit and swivel  
 1:00 PM- Started drilling surface plug  
 6:30 PM- SDFN  
  
 7/21/20  
 7:00 AM- Tagged @ 372'  
 10:00 AM- @550' bits of plastic circulated out  
 12:15 PM- Tagged @ 665' then broke through cement @ 700'  
 1:00 PM- continued drilling  
 6:00 PM- Drilled to 1715' then SDFN  
  
 7/22/20  
 6:00 AM- Pressure test @ 300 psi. Lost pressure very quickly  
 7:00 AM- continued drilling circulated out @ 1850'  
 10:00 AM- Tagged @ 2740'. Circulated out parafin. Bradenhead built up pressure to 60 psi  
 10:30 AM- POOH  
 11:30 AM- Run CBL from 2700'-0'. CBL appears to show a lot of free pipe.  
 1:30 PM- CIBP set @ 2700'  
 2:30 PM- Set 6 sacks on top of CIBP  
 3:30 PM- Perf @ 1550'. Set CR @ 1492'  
 4:00 PM- tbg in hole  
 4:30 PM- Could not build up enough pressure to sting through CR  
 4:50 PM- Set plug on top of CR from 1492'-1400'  
 6:18 PM- Injection test. Good circulation  
 6:40 PM- Combined plugs 3 & 4. Perf @ 1330' Set CICR @ 1275'  
 6:50 PM- Set plug with 154 sacks 15.8 wt from 1330'-790'. Good circulation no loss.  
 8:00 PM- Perf @ 475' set CICR @ 420'  
 8:45 PM- Pumped 36 sacks @ 15.8 wt. 30 sacks below & 6 sacks on top.  
 9:00 PM- Perf @ 120'  
 9:30 PM- Set plug 120'-0' with 97 sacks cement. Lost cement  
 10:00 PM- SDFN  
  
 7/23/20  
 8:00 AM- Cut wellhead  
 9:00 AM- Surface plug dropped over night. Tagged @ 17' inside 5 1/2" csg and tagged @ 18' outside csg.  
 9:30 AM- Topped out with cement to surface  
 10:30 AM- Plate welded.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
This inspection is a summary observation of the plugging and abandoning of the well. This well was part of the Red Mesa 9 OWP project.	durana	08/28/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694600086	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234617">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234617</a>