

Inspection Photos  
Operator: WPX Operating  
API: 067-05431  
Date: 8/18/2020



Photo 1. View of the project area from the northwestern edge facing center. Plugged well marker observed.



Photo 2. View of the northern project area, revegetation is progressing with rubber rabbitbrush, crested wheatgrass, and western wheatgrass.






Photo 3. View of revegetation in the northern project area. Revegetation is approaching reclamation standards, however, approximately 200-300 Russian knapweeds interspersed within this portion of the reclamation area. Revegetation is progressing with crested wheatgrass, rubber rabbitbrush, squirreltail, and purple asters.





Photo 4. Another view of Russian knapweeds within the northern project area.





Photo 5. View of reference area comprised of sagebrush shrubland, with black sage and big sagebrush, scattered pinyon and ponderosa pine trees, with an understory of squirreltail, blue grama, purple three-awn, penstemons, and purple asters.