

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/28/2020

Submitted Date:

08/28/2020

Document Number:

696103621

FIELD INSPECTION FORM

Loc ID 306148 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285818	WELL	SI	03/01/2019	OW	123-24060	CBO 24-32	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / CEMENTING** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Plugging Operations / Cementing in progress. Final plug.
Battery: Inactive | Shut-down.
Inactive Battery SE corner GPS coordinates: 40.523081, -104.460872

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Workover jobsite safety signage present.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 285818 Type: WELL API Number: 123-24060 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Next Tier Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 1620' - 0' Cement Volume (sx): 353 sxs

Good Return During Job: YES Cement Type: Class "G-Neat" 15.8#

Comment: [Workover Contractor: Ensign. Rig #354.](#)
[Cementing Contractor: Nex Tier.](#)

Reference:
[Form 42 doc. #402477023 indicates notice of plugging start date: 08/27/2020. Approved.](#)
[Form 6 doc. #402459588 Notice of intent to Abandon date: 08/10/2020. Approved.](#)

[Crew traveled to location crew held safety meeting check pressure well was dead this am, function test bop test good. P/U mule shoe rig with 52jnt 10' sub 2-3/8" J-55 tubing to 1620'. R/U pump conditioned annulus for 45min pumping 2bbl/min with 50-psi good circulation clean water in returns R/D pump. MIRU Nextier cementers held safety meeting. Load lines with 1bbl pressure test 1500psi. Pumped 5bbl fresh ahead mix/pump 337sxs\(69bbl\) G-Neat 15.8# cement from 1620'-surf returned 1bbl cement to surface. R/D cementers. L/D 10' sub, 52Jnts to trailer. Tied cementers onto casing top off cement to surface with 16sxs\(3.2BBL\) G-Neat 15.8# cement, R/D wash up cementers. R/D work floor tubing equipment, N/D BOP 8-5/8" spool. Installed 8-5/8" cap SWI. R/D rig pump/tank. Installed well fence. Crew cleaned location. Move rig/equip off location.](#)

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 08/28/2020 at approximately 08:43 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: CBO-67N63W /32SESW Location ID: 306148 Well Name: CBO 24-32 API: 05-123-24060 Location County: Weld County, Colorado Weather: Mostly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations / Cementing in progress. Final plug. Battery: Inactive Shut-down. Inactive Battery SE corner GPS coordinates: 40.523081, -104.460872</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	08/28/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103622	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234959