

Inspection Photos  
Operator: Hilcorp Energy  
API: 067-08737  
Date: 8/27/2020



Photo 1. View of the project area from the southwestern edge facing center.



Photo 2. View of the southern fill slope facing westward. Dense Russian thistle and kochia growing up to 4-feet tall within the reclamation areas.





Photo 3. View of the northern cut-slope and revegetation areas. Some desirable vegetation becoming established, although many areas remain sparse/bare.



Photo 4. View of reclamation area in the northern project area. Scattered germination of desirable species observed, however significant portions of the area remain bare.





Photo 5. View of erosional rilling and sediment deposition that continues on the well pad cut-slopes.



Photo 6. View of continued erosion occurring within the southwestern project area.





Photo 6. View of reference area vegetation comprised of black sagebrush shrubland with grasses and forbs such as Indian ricegrass, lanceleaf buckwheat, and needleandthread grass.