

Inspection Photos

API: 071-07186

Operator: TIMBER CREEK OPERATING

Inspection Date: 8/27/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07186 | Date: 8/27/2020

Inspection Photos



Photo 1. The road has been regraded near the location and the culvert is maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07186 | Date: 8/27/2020

Inspection Photos



Photo 2. Facing west near the location. The erosion has been repaired and road regraded. BMP's may be needed along the road to dissipate stormwater flow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07186 | Date: 8/27/2020

Inspection Photos



Photo 3. There is straw blanket installed along a portion of the cut slope.



Inspection Photos



Photo 4. The berms along the bottom of the fill slope have been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07186 | Date: 8/27/2020

Inspection Photos



Photo 5. It appears noxious weeds are wilted from herbicide treatment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07186 | Date: 8/27/2020

Inspection Photos



Photo 6. Further along the road noxious weeds appear to have been controlled however, the weeds have begun to produce and disperse seed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07186 | Date: 8/27/2020