

Construction and Stormwater Inspection

August 26, 2020

Operator: GULF EXPLORATION LLC- #10728

Location ID: 456859

Inspection Document #: 697501941

Weld County, CO

SESW Section 10 T7N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Black Powder /2
Location ID: 456859



Photo 1. Photo taken from the access road, facing North. Photo illustrates the Operator sign at the entrance of location.

Inspection Photos
Location Name: Black Powder /2
Location ID: 456859



Photo 2. Photo taken from the northeastern location, facing Southeast. Photo illustrates stormwater BMPs- retention area, and a stabilized outlet. Stormwater BMP areas will likely need to be stabilized due to the sandy soil.

Inspection Photos
Location Name: Black Powder /2
Location ID: 456859



Photo 3. Photo taken from the northeastern location, facing West. See comments under Photo 2.

Inspection Photos
Location Name: Black Powder /2
Location ID: 456859



Photo 4. Photo taken from the northwestern location, facing South. Photo illustrates the topsoil stockpile which has been temporarily stabilized with equipment tracking. Wattle BMPs have been installed around the outer perimeter of the stockpile.

Inspection Photos
Location Name: Black Powder /2
Location ID: 456859



Photo 5. Photo taken from the northwestern location, facing South. See comments under Photo 2. Note: there is a vegetated buffer between the pad and the outer perimeter BMP.

Inspection Photos
Location Name: Black Powder /2
Location ID: 456859



Photo 6. Photo taken from the southwestern location, facing East. See comments under Photo 5.

Inspection Photos
Location Name: Black Powder /2
Location ID: 456859



Photo 7. Photo taken from the southeastern location, facing North. See comments under Photo 5.