

Inspection Photos
Operator: Hilcorp Energy
API: 067-06933
Date: 8/27/2020



Photo 1. View of the project area from the southwestern edge facing center.



Photo 2. View of the southern fill slope facing westward. Vegetation is becoming established with fourwing saltbush, rubber rabbitbrush, and western wheatgrass.




Photo 3. View of Russian knapweeds that appear to be herbicide treated within the project area.



Photo 4. View of Russian knapweeds that do not appear to be herbicide treated within the project area.



Photo 5. View of reference area vegetation comprised of pinyon juniper woodland with understory of big sagebrush, squirreltail, and antelope bitterbrush.