

Inspection Photos
Operator: Hilcorp Energy
API: 067-06512
Date: 8/27/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing outside of irrigation alignment, with western wheatgrass and smooth brome.



Photo 3. View of dense kochia debris, up to 3-feet tall, growing on the well pad, needs to be removed and properly disposed of.



Photo 4. View of reference area vegetation comprised of irrigated grass field with grasses such as orchard grass as well as sedges and rushes such as Baltic rush.