

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/31/2020

Submitted Date:

08/31/2020

Document Number:

699302450

**FIELD INSPECTION FORM**

Loc ID 317639 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
 Name of Operator: KP KAUFFMAN COMPANY INC  
 Address: 1675 BROADWAY, STE 2800  
 City: DENVER State: CO Zip: 80202

**Findings:**

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239655	WELL	PR	05/04/1972	OW	123-07443	MARTIN T. HART 1	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

**Good Housekeeping:**

Type	WEEDS		
Comment:	weeds overgrown around Electric panel, transformers and meter box.		
Corrective Action:	comply with Rule 603.f		Date: 09/14/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	angle iron, hog fence		
Corrective Action:			Date:

**Equipment:**

Type:		#		corrective date
Ancillary equipment		# 1		
Comment:	electric panel, meter box & transformers			
Corrective Action:				Date:
Prime Mover		# 1		
Comment:	electric motor			
Corrective Action:				Date:
Bradenhead		# 1		
Comment:	appears to be plumbed to surface			
Corrective Action:				Date:
Pump Jack		# 1		
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:	<input type="text"/>		

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 239655 Type: WELL API Number: 123-07443 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Monday 8/31/2020 at approximately 1100 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: center;">Martin T. Hart #1 at API #05-123-07443 in Weld County Colorado.</p> <p>While there, I observed a wellsite.                      During this inspection the following possible compliance issue was observed:                      603.f housekeeping: Weeds overgrown around Electric panel transformers and meter box.                      CA date 9/14/2020 see photo 4.                      See attached photos.                      Location is dry, weather is clear.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	08/31/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302451	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5235925">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5235925</a>