

**Inspection Photos**  
**Location Name: HILL RANCH 35-14**  
**API#: 05-071-08252**  
**INSP. #: 695103244**



**PHOTO 1: LOCATION**



**PHOTO 2: WELL SIGN**

## Inspection Photos

Location Name: HILL RANCH 35-14

API#: 05-071-08252

INSP. #: 695103244



Colorado Oil & Gas Conservation Commission  
37.03667, -104.96497, 2615.0m, 239°  
2020/08/24 12:56:00



Colorado Oil & Gas Conservation Commission  
37.03667, -104.96497, 2615.0m, 239°  
2020/08/24 12:56:06

**PHOTO 3: TBG PACKING IS LEAKING PRODUCED WATER. REPAIR PACKING (THERE IS LITTLE TO NO STANDING FLUID ON THE GROUND), COMPLY WITH RULE 907.c. AND Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA DATE 8-25-20.**

**PHOTO 4: CLOSER IMAGE OF PACKING LEAK, FOLLOW GUIDANCE GIVEN ON PHOTO 3.**