

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2020

Submitted Date:

08/24/2020

Document Number:

688308416

FIELD INSPECTION FORMLoc ID 416953 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10706

Name of Operator: D90 ENERGY LLC

Address: 202 TRAVIS STREET #402

City: HOUSTON State: TX Zip: 77002

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
James, Cole	719-892-0378	cj0378@hotmail.com	Pumper
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent
Kosola, Jason		jason.kosola@state.co.us	COGCC EPS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416957	WELL	IJ	10/20/2017	DSPW	073-06413	JOHN CRAIG 7-2	SI

General Comment:Spill Inspection

The produced water tank overtopped due to slow injection into the injection well. The spill was in containment and not reportable however Rule 907 still applies to the proper disposal of stained soils/gravel inside of containment. Inspector contacted COGCC EPS. Operator said that the spill would be cleaned up and tanks cleaned on 8/25 and 26. The tank battery is associated with the John Craig 6-2 well (073-06477) but the 7-2 was the reason for the spill.

Doc#402190896 Form 10 (CO) (CC) IN PROCESS 03/25/2020 D90 ENERGY LLC

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			
PW/CO	Tank	<= 1 bbl			
Comment:	Produced water tank overtopped spilling into containment (metal berms).				
Corrective Action:	For localized stained soils or oily waste - Properly dispose of oily waste in accordance with 907.e.				Date: 09/04/2020

In Containment: Yes

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 416957 Type: WELL API Number: 073-06413 Status: IJ Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402474273	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231244
688308465	D90 Energy John Craig 7-2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5231242