

Inspection Photos

API: 071-06488

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/31/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06488 | Date: 8/31/2020

Inspection Photos



Photo 1. Facing north along the access road. Vegetation has not adequately established along the road. Soils may be compacted in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06488 | Date: 8/31/2020

Inspection Photos



Photo 2. Facing north along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06488 | Date: 8/31/2020

Inspection Photos



Photo 3. Facing back to the south along the access road. There is some riling occurring in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06488 | Date: 8/31/2020

Inspection Photos



Photo 4. Facing northeast along the reclaimed access road. Vegetation is well established along this portion of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06488 | Date: 8/31/2020

Inspection Photos



Photo 5. Facing east toward the location. Vegetation is well established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06488 | Date: 8/31/2020

Inspection Photos



Photo 6. Facing west toward the location. Vegetation is well established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06488 | Date: 8/31/2020

Inspection Photos



Photo 7. Facing southwest adjacent to the access road at the undisturbed vegetation reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06488 | Date: 8/31/2020