

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/01/2020

Submitted Date:

09/01/2020

Document Number:

700701458

FIELD INSPECTION FORM
 Loc ID 334586 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277112	WELL	PR	10/23/2006	GW	045-10601	HMU 4-12 (K4DW)	PR
277113	WELL	PR	11/16/2005	GW	045-10602	GMR 4-4B(K4DW)	PR
277114	WELL	PR	06/06/2006	GW	045-10603	HMU 4-13 (K4DW)	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 9/1/20 at approximately 1300, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus K4DW, at Location # 334586 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 3		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 277112 Type: WELL API Number: 045-10601 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 277113 Type: WELL API Number: 045-10602 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 277114 Type: WELL API Number: 045-10603 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Berms		Culverts				
Ditches		Ditches				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701467	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5236961