

Inspection Photos

Loc#418843

Operator: GRMR

Insp#: 692402482

Insp Date: 8/27/2020



Photo#1:
Overview of Location from entry to North.

August 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR Durham Loc#418843



Photo#2:
Overview of Location to South.

August 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR Durham Loc#418843



Photo#3:
Views of fill slope and weed establishment ; Russian thistle predominate.

August 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR Durham Loc#418843



Photo#4:
Cut slope erosion and sediment run on.



Photo#5:
Cut slope erosion and sediment run on.

August 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR Durham Loc#418843



Photo#6:
Erosion at pad edge; view down fill slope.



Photo#7:
Washout; view from base of fill. Insert of top of slope
and believed tunnel/wormhole origination.

August 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR Durham Loc#418843



Photo#8:
Concrete equipment base remains on site.



Photo#9:
Anchors, electrical unit remain on site.

August 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR Durham Loc#418843