

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	location notification signs are adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Ag fence		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240630 Type: WELL API Number: 123-08418 Status: SI Insp. Status: SI

Cement

Cement Contractor

Contractor Name: _____ Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 7680 Cement Volume (sx): 2

Good Return During Job: _____ Cement Type: neat

Comment: NU The Wireline Group Logging Truck and Equipment. PU CIBP and RIH and set @ 7680' with 2 sxs cement on top.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 9/1/2020 at approximately 1200- 1500 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Frank Guertner Gas unit 1 at API #05-123-08418 in Weld County Colorado.</p> <p>While there, I observed Plugging operation. Basic Rig 1509 RU over well. RU/NU The Wireline Group Logging Truck and Equipment, PU CIBP and RIH and set @ 7680' with 2 sxs cement on top.</p> <p>During this inspection no compliance issues were observed: See attached photos. Location is dry, weather is clear. I spoke with Rigo Cintora Field Foreman with Kerr McGee about plugging operations (plug/perf depths, cement volumes) throughout the day. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	09/01/2020