

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/02/2020

Submitted Date:

09/02/2020

Document Number:

697001984

FIELD INSPECTION FORMLoc ID 328416 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248167	WELL	PA	04/06/2015	GW	123-15965	EHRlich 23-11	PA
426467	WELL	PR	08/01/2018	OW	123-34700	EHRlich PC O 23-67HN	SI
426468	WELL	PR	11/15/2012	OW	123-34701	EHRlich PC O 23-69HN	SI

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:	Methanol systems		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease road entrance		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 2		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	VRT lacks placards. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	12/04/2020

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe and panel		
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 3		corrective date
Comment:	Calibration cards are outdated. See attached photo.		
Corrective Action:	Measure gas per Rule 329.	Date:	12/04/2020
Type: Bradenhead	# 2		

Comment:		Bradenhead valves are exposed at surface.		Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 7				
Comment:				Date:	
Corrective Action:				Date:	
Type: Emission Control Device	# 4				
Comment:				Date:	
Corrective Action:				Date:	
Type: Pig Station	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:		Natural gas engine on VRU		Date:	
Corrective Action:				Date:	
Type: VRT	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: VRU	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	#				
Comment:		Automation array, solar array, methanol systems in secondary containment, ECD scrubbers		Date:	
Corrective Action:				Date:	
Type: Plunger Lift	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 3				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:
Contents	#	Capacity	Type	Tank ID
PRODUCED WATER	3	<100 BBLs	BV CONCRETE	
Comment: 60 bbls				
Corrective Action:				Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:
Contents	#	Capacity	Type	Tank ID
CRUDE OIL	5	300 BBLs	STEEL AST	
Comment:				
Corrective Action:				Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 248167 Type: WELL API Number: 123-15965 Status: PA Insp. Status: PAFacility ID: 426467 Type: WELL API Number: 123-34700 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____Facility ID: 426468 Type: WELL API Number: 123-34701 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 9/2/2020 at approximately 09:00 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Noble Energy Ehrlich PC O 23-69HN Pad location #328416 in Weld County, Colorado.</p> <p>While there, I observed that the VRT lacked all placards and the gas sales meter calibration cards were outdated. During this inspection the following possible compliance issues were observed: Rule 210.d. with a corrective action date of 12/4/2020, Rule 329 with a corrective action date of 12/4/2020.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	09/02/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697001985	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5237764