

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: 4' barb wire

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment # 1

Comment: electirc

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: electric motor

Corrective Action:

Date:

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 241423 Type: WELL API Number: 123-09212 Status: PR Insp. Status: PR

Producing Well

Comment:	PR	
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were sunny and slight wind.	medinaj	09/03/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501665	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5238797