

Inspection Photos

Operator: BP America
API: 067-07246
Date: 9/2/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing here with western wheatgrass and smooth brome facing northward.



Photo 3. View of the northwestern project area. Bare soils need stabilization.



Photo 4. View of the well pad cut-slope. Additional stabilization measures are needed to stabilize bare soils.



Photo 5. View of reference area vegetation comprised of mixed gambel oak and ponderosa pine woodland, with pinyon and juniper trees, shrubs such as mountain mahogany and antelope bitterbrush, as well as grasses and forbs such as Indian ricegrass, James galleta, and bricklebush.