

**Inspection Photos**  
**Operator: Hilcorp Energy**  
**API: 067-07593**  
**Date: 9/1/2020**



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing, largely with western wheatgrass and sunflowers.



Photo 3. View of the northeastern cut-slope. It appears revegetation was conducted here as straw mulch is present. Grasses are becoming established.



Photo 4. View of the eastern project area from the southeastern corner facing northward. Unused equipment (trailers) parked on the well pad. If portions of the project area are not needed for production operations, then interim reclamation needs to be conducted.



Photo 5. View of reference area vegetation comprised of ponderosa pine forest with an understory of gambel oaks, Oregon grape, and Sandberg bluegrass.