

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /29SWNW

Location ID: 312424



Photo #1826 from entrance to location



Photo #1166 photo from inspection #699801090 conducted on 5/13/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /29SWNW

Location ID: 312424



Photo #1827 Unused meter run.



Photo #1170 photo from inspection #699801090 conducted on 5/13/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /29SWNW

Location ID: 312424



Photo #1828 Flow line riser not LO/TO.



Photo #1168 photo from inspection #699801090 conducted on 5/13/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /29SWNW

Location ID: 312424



Photo #1169 photo from inspection #699801090 conducted on 5/13/20.



Photo #1830 Multiple unmarked deadman.