

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW

Location ID: 312424



Photo #1831 from entrance to location



Photo #1237 from inspection #699801142 conducted on 5/21/20.



## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW

Location ID: 312424



Photo #1832 Flow line risers not LO/TO.



Photo #1236 from inspection #699801142 conducted on 5/21/20.

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW

Location ID: 312424



**Photo #1833 Debris inside pit.**