

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID: 312424



Photo #1834 from entrance to location



Photo #1835 from entrance to location



## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID: 312424



**Photo #1836 Debris inside pit.**



**Photo #1837 Debris around equipment.**