

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /35SENW

Location ID: 312511



Network time is not synchronize
Local: Sep 3, 2020 at 12:53:04 PM MD



Network: May 21, 2020 at 1:16:54 PM MD
Local: May 21, 2020 at 1:16:52 PM MD
+39.3173, -108.299

Photo #1841 from NW corner of location

Photo #1243 from inspection #699801146 inspection conducted on 5/21/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /35SENW

Location ID: 312511



Photo #1842 Debris inside both pits



Photo #1244 from inspection #699801146 inspection conducted on 5/21/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /35SENW

Location ID: 312511



Photo #1843 Debris inside both pits



Photo #1247 from inspection #699801146 inspection conducted on 5/21/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /35SENW

Location ID: 312511



Photo #1844 Unused meter run.