

# Inspection Photos

Operator: BP America  
API: 067-06357  
Date: 9/1/2020



Photo 1. View of the project area from the southwestern corner facing center.





Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with grasses such as smooth brome and western wheatgrass.





Photo 3. View of Scotch thistles that appear to be herbicide-treated within the project area. Approximately 200 herbicide-treated individuals observed.





Photo 4. View of reference area vegetation comprised of mixed gambel oak and ponderosa pine woodland, with pinyon and juniper trees, shrubs such as mountain mahogany and antelope bitterbrush, as well as grasses and forbs such as Indian ricegrass, James galleta, and bricklebrush.