

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2020

Submitted Date:

09/04/2020

Document Number:

694500223

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: NEIDEL, KRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
 OGCC Operator Number: 16690  
 Name of Operator: CHEVRON PIPELINE COMPANY  
 Address: 2750 COUNTY ROAD 102  
 City: RANGELY State: CO Zip: 81648

**Findings:**  
2 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Eggert, Derek	281-753-0816	dhyg@chevron.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449632	SPILL OR RELEASE	CL	09/18/2017		-	SPILL/RELEASE POINT	EI

**General Comment:**  
 On 8/26/2020 COGCC Staff, Kris Neidel inspected the Rangely C-4 spill path. Spill 449632 and Remediation #10149. Weather was partly cloudy, hot and 92 degrees. The area referred to as the bowl is near the source of the spill, oil had more time to soak into the ground in this area. Initial Spill response removed heavily contaminated leaving a larger depression in the ground. Soil in the bowl has been undergoing in situ treatment (water, amendment and tilling). Chevron staff was on location to collect soil samples at 1 foot BGS (below ground surface) and 2 feet BGS in four location around the perimeter of the bowl. The north west and the north east bowl samples had detectable hydrocarbon odor,. Samples were also collected at 6 locations in the flow path, just down grade from the bowl. These samples were collected at 1 foot BGS and 2 foot BGS. None of these samples had detectable odor. Samples were collected from other areas described in the remediation project documents, in division 3. No detectable odor was present in division 3 samples. General comments on the spill path: Areas of the spill path that have been granted 'no further action' have vegetation. Chevron Pipeline has been working with the BLM on revegetation and reclamation in these areas. Areas that have remaining impact have continued to be tilled, the surface is soft from tilling and free of vegetation (also believed to be from tilling). The entire spill path is free of any visible hydrocarbon. See attached Photos.

**Inspected Facilities**

Facility ID: 449632 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500224	photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5239717">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5239717</a>