

Inspection Photos

API: 071-09244

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/2/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09244 | Date: 9/2/2020

Inspection Photos



Photo 1. Facing northwest along the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09244 | Date: 9/2/2020

Inspection Photos



Photo 2. Facing northwest along the access road which has not been reclaimed. There is signs of erosion as the road ascends to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09244 | Date: 9/2/2020

Inspection Photos



Photo 3. Facing west toward the location. The location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09244 | Date: 9/2/2020

Inspection Photos



Photo 4. Facing west toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09244 | Date: 9/2/2020

Inspection Photos



Photo 5. Facing north toward the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09244 | Date: 9/2/2020

Inspection Photos



Photo 6. The cut slope is not stabilized and there is signs of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09244 | Date: 9/2/2020

Inspection Photos



Photo 7. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09244 | Date: 9/2/2020