

Inspection Photos

API: 071-08562

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/2/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08562 | Date: 9/2/2020

Inspection Photos



Photo 1. Facing west toward the beginning of the access road. The access road has not been recontoured and reclaimed and there is erosion occurring.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08562 | Date: 9/2/2020

Inspection Photos



Photo 2. Facing west along the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08562 | Date: 9/2/2020

Inspection Photos



Photo 3. There is erosion occurring along the access road which is not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08562 | Date: 9/2/2020

Inspection Photos



Photo 4. Facing southwest along the access road near the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08562 | Date: 9/2/2020

Inspection Photos



Photo 5. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08562 | Date: 9/2/2020

Inspection Photos



Photo 6. Facing southeast along the fill slope which has not been recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08562 | Date: 9/2/2020

Inspection Photos



Photo 7. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08562 | Date: 9/2/2020

Inspection Photos



Photo 8. Facing east at the south side of the location. This area matches the contours. The south side of the location would likely not require recontouring.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08562 | Date: 9/2/2020

Inspection Photos



Photo 9. Facing northwest toward the location. The cut slope has not been recontoured to the approximate contours.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08562 | Date: 9/2/2020

Inspection Photos




Photo 10. There is a guy line anchor found at the flat portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08562 | Date: 9/2/2020

Inspection Photos



Photo 11. Facing northwest at the northern portion of the location. This fill slope area should be pushed back into the cut slope to match the approximate contours.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08562 | Date: 9/2/2020