

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/03/2020

Submitted Date:

09/04/2020

Document Number:

701001264

FIELD INSPECTION FORM

Loc ID 321015 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10626
Name of Operator: DOVER ATWOOD CORPORATION
Address: 1875 HARSH AVENUE SE
City: MASSILLON State: OH Zip: 44646

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	BACA Inspections
Crane, Rocky	(719) 529-0682	rockycrane@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205785	WELL	PR	05/01/2020	GW	009-06200	ROLLINS RUTHERFORD 1A-20	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Lease sign by meter shed		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Wire fence around unit and wellhead		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Electric panel and cathodic rectifier		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor. Belts removed at time of inspection		
Corrective Action:			Date:
Type: Vertical Separator	# 0		
Comment:	Removed from location		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Meter run is 500' west of wellhead		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Parkersburg unit		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	200 BBLs	Open Top		37.333410,-102.406800

Comment: Tank removed from location

Corrective Action: _____ Date: _____

Paint

Condition _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: _____

Corrective Action: _____ Date: _____

Venting:

Yes/No		
Comment:		
Corrective Action:		Date: _____

Flaring:

Type	
Comment:	
Corrective Action:	Date: _____

Inspected Facilities

Facility ID: 205785 Type: WELL API Number: 009-06200 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Meter run is 500' west of wellhead](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	Pass			

Comment: [Access is grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701001265	Meter shed photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5240014
701001266	Wellhead photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5240015