

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/28/2020

Submitted Date:

08/31/2020

Document Number:

696103636

FIELD INSPECTION FORM
 Loc ID 305508 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|-----------------|
| , | | cogccinspection@pdce.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 278723 | WELL | SI | 03/01/2020 | OW | 123-23073 | HOWARD LAKE 21-9 | SI |

General Comment:

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (332473, 305508).

(Well(s): 1: Temporarily Abandoned | TA ;1: Shut-In | SI).

Centralized Battery formerly served 1 Location ID (305382).

(Well(s): 1: Plugged & Abandoned | PA).

 Refer to Field Inspection Report doc. #696103633 and/or Location ID #332473
 for Battery / Facility, Equipment info.

| Location | | | | |
|--|---|--------|--|------------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Adequate | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | WELLHEAD | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type | | | | |
| Comment: | Refer to Field Inspection Report doc. #696103633 and/or Location ID #332473 for Battery / Facility, Equipment info. | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: _____ |
| Good Housekeeping: | | | | |
| Type | WEEDS | | | |
| Comment: | Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Corrective Action date: 09/14/2020. See photo #1. | | | |
| Corrective Action: | Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. See photo #1. | | | Date: 09/14/2020 |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | | | | |
| Comment: | Refer to Field Inspection Report doc. #696103633 and/or Location ID #332473 for Battery / Facility, Equipment info. | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | Iron panel. | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| Type: Plunger Lift | # 1 | | | corrective date |
| Comment: | | | | |

| | | | |
|--------------------|---|-------|--|
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears plumbed to surface. | | |
| Corrective Action: | | Date: | |
| Type: | # | | |
| Comment: | Refer to Field Inspection Report doc. #696103633 and/or Location ID #332473 for Battery / Facility, Equipment info. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|--|----------|---------------------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| | | | CENTRALIZED BATTERY | | 40.504875,-104.563221 |
| Comment: | <p>Centralized Battery serves 2 Location IDs (332473, 305508). (Well(s): 1: Temporarily Abandoned TA ; 1: Shut-In SI).</p> <p>Centralized Battery formerly served 1 Location ID (305382). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696103633 and/or Location ID #332473 for Battery / Facility, Equipment info.</p> | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 278723 | Type: | WELL | API Number: | 123-23073 | Status: | SI | Insp. Status: | SI |
| Idle Well | | | | | | | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: PRODUCTION RECORDS | | | | | | | | | |
| Comment: Shut-In SI. Observed production valves shut. COGCC records indicate last production: 02/2020. | | | | | | | | | |
| Corrective Action: Date: | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary:</p> <p>On FRI 08/28/2020 at approximately 14:42 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: HOWARD LAKE-66N64W /9NENW Location ID: 305508 Well Name: Howard Lake 21-9 API: 05-123-23073 Location County: Weld County, Colorado Weather: Mostly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (332473, 305508). (Well(s): 1: Temporarily Abandoned TA ; 1: Shut-In SI).</p> <p>Centralized Battery formerly served 1 Location ID (305382). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696103633 and/or Location ID #332473 for Battery / Facility, Equipment info.</p> <p>During this inspection the following possible compliance issues were observed: 1.) Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 09/14/2020. See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p> | evinsb | 08/31/2020 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402479045 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5236060 |

| | | |
|-----------|-------------|---|
| 696103637 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5236058 |
|-----------|-------------|---|

