

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Excavation around Fitzhugh #7 well head.



Impacted material in sidewall of excavation.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Fitzhugh #6.



Excavation near Fitzhugh #7.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Second land farm treatment cell to the north of the first.



Impacted material from excavation near the Fitzhugh #7 in newly created land farm treatment area.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



View of north treatment cell with excavation near Fitzhugh #7 in background.



Sample location in southern treatment cell.