

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Weeds present near pump jack and within secondary containment for AST.



Equipment and trailers stored on site.

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Well head is stained and wet.



Weeds present within secondary containment