

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/02/2020

Submitted Date:

09/09/2020

Document Number:

688800794

FIELD INSPECTION FORM

Loc ID 320860 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 900
Name of Operator: ALAMOSA DRILLING INC
Address: 8150 N. CENTRAL EXPY - STE 750
City: DALLAS State: TX Zip: 75205-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205258	WELL	PR	06/01/2020	OW	007-06136	CHAVEZ 2	EI

General Comment:

On September 2, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Inc. Chavez #2. For the most recent field inspection report of this facility, please refer to document #688800132.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to fencing around pump jack and well head.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Stained soil around well head.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>10/09/2020</u>

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Post and wire fencing around pump jack and well head.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		37.018064,-106.875094

Comment:	AST shared with Chavez #1.	
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Inadequate
Comment:	Weeds present within secondary containment berm.			
Corrective Action:	Comply with Rule 603.f.			Date: 09/16/2020

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 205258 Type: WELL API Number: 007-06136 Status: PR Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Piles	Inadequate	37.017682	-106.873857
Comment	Impacted material from Spill/Release at the Albert Martinez #1 tank battery remains near the Chavez #2. The operator shall remove this impacted soil immediately.			
Corrective Action	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contact COGCC EPS staff.			Date: 09/11/2020

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On September 2, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Inc. Chavez #2. For the most recent field inspection report of this facility, please refer to document #688800132.</p> <p>The well head and surrounding soil is stained.</p> <p>Stock piled soil from the Albert Martinez #1 tank battery has not been removed. This impacted soil shall be removed and properly disposed of immediately.</p>	hughesjo	09/09/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800795	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5242581