

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/10/2020

Submitted Date:

09/10/2020

Document Number:

699501688

FIELD INSPECTION FORMLoc ID 446474 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10110

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC

Address: 1001 17TH STREET #2000

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446475	WELL	PR	11/01/2019	OW	123-43337	Sack 21-4-12HC	PR
455341	WELL	PR	11/01/2019	OW	123-46994	Sack KE 21-242HC	PR
455342	WELL	PR	09/01/2018	LO	123-46995	Sack KE 21-319HC	PR
455343	WELL	PR	11/01/2019	OW	123-46996	Sack KE 21-322HN	PR
455344	WELL	PR	11/01/2019	OW	123-46997	Sack KE 21-279HN	PR
455345	WELL	PR	11/01/2019	OW	123-46998	Sack KE 21-282HN	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Pig Station

1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

6

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: electric / automation

Corrective Action:

Date:

Type: VRU

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

6

Comment:

Corrective Action:

Date:

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: VRT

1

Comment:

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:	Fuel gas for compressor		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Gas Lift Prime Mover		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	500 BBLs	FIBERGLASS AST		,	
Comment:	533 BBL					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tanks.			
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	9	500 BBLs	STEEL AST		,	
Comment:	533 BBL					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 446475 Type: WELL API Number: 123-43337 Status: PR Insp. Status: PRFacility ID: 455341 Type: WELL API Number: 123-46994 Status: PR Insp. Status: PRFacility ID: 455342 Type: WELL API Number: 123-46995 Status: PR Insp. Status: PRFacility ID: 455343 Type: WELL API Number: 123-46996 Status: PR Insp. Status: PRFacility ID: 455344 Type: WELL API Number: 123-46997 Status: PR Insp. Status: PRFacility ID: 455345 Type: WELL API Number: 123-46998 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were snow/rain muddy location.	medinaj	09/10/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501689	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5244223