

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/01/2020

Submitted Date:

09/10/2020

Document Number:

694500227

FIELD INSPECTION FORM

 Loc ID 324695 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10112
 Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
 Address: 5057 KELLER SPRINGS RD STE 650
 City: ADDISON State: TX Zip: 75001
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 1 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa	720-257-2302 303-244-8114	ABeard@foundationenergy.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212457	WELL	SI	05/01/2019	OW	057-06351	SCHOCK-FEDERAL 1	EI
324695	LOCATION	AC			-	SCHOCK-FEDERAL-610N80W 31SWSE	EI
446048	PIT	AC			-	SCHOCK-FEDERAL 1 PIT 1	EI
446049	PIT	AC			-	SCHOCK-FEDERAL 1-PIT 2	EI

General Comment:

On 9/1/2020 COGCC Staff, Kris Neidel inspected the; Schock Federal, two related pits and Spill 476917. The pits are part of Remediation #15805. Weather was clear, windy and 50 degrees. Pits were sampled at 18" below the bottom of the pit and the pit wall. Both pit bottoms consisted of dense clay bottom. No hydrocarbon staining was observed in the pits. No hydrocarbon odor was detectable in the pit soil. A tinhorn separator was observed near pit 446048, the tinhorn was not sampled. The Tinhorn is scheduled to be removed and underlying soil sampled on 9/15/2020. Samples were also collected for spill #476917. The spill sample collected near the wellhead had gravel fill that had been brought in to bring the pad to grade, the fill was removed with a shovel to get to soil that had been exposed to the spill. The operator shall continue to communicate with COGCC staff via eForms. Sample data shall be submitted on an eForm 27 within 30 days of receiving data from the lab. See attached Photos.

Inspected FacilitiesFacility ID: 212457 Type: WELL API Number: 057-06351 Status: SI Insp. Status: EIFacility ID: 324695 Type: LOCATION API Number: - Status: AC Insp. Status: EIFacility ID: 446048 Type: PIT API Number: - Status: AC Insp. Status: EIFacility ID: 446049 Type: PIT API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500228	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5244374