

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/25/2020

Submitted Date:

08/25/2020

Document Number:

699801673**FIELD INSPECTION FORM**Loc ID 324471 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, BLM		jbyers@blm.gov	
, SG Interests		inspection@sginterests.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275738	WELL	TA	12/01/2017	GW	051-06059	FEDERAL 11-90-35#1	TA

General Comment:**COGCC Inspection Report Summary**

On Tuesday 8/25/20 at approximately 11:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at SG INTERESTS I LTD FEDERAL-611S90W /35SWNE, Location #324471 in Gunnison County Colorado. Refer to document #699801460 inspection conducted on 7/16/20. Not all previous corrective actions have been completed.

During this inspection the following possible compliance issues were observed: Multiple places with unused equipment. See photo #1777 and #1778 with a corrective action date of 11/25/20. Multiple places with weeds and debris on location. See photo #1779 and #1780 with a previous corrective action date of 7/30/20. Flow line riser not LO/TO. See photo #1781 with a corrective action date of 11/25/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Multiple places with weeds and debris on location. See photo #1779 and #1780		
Corrective Action:	Production facilities, shall be kept free of weeds and debris.		Date: 07/30/2020
Type	UNUSED EQUIPMENT		
Comment:	Flow line riser not LO/TO. See photo #1781		
Corrective Action:	Flow line risers not LO/TO are considered unused equipment. Properly LO/TO flowline riser or remove riser.		Date: 11/25/2020
Type	STORAGE OF SUPL		
Comment:	Multiple places with unused equipment. See photo #1777 and #1778		
Corrective Action:	Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove all unused equipment from location.		Date: 11/25/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Livestock panels		

Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pump in pump house.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 275738 Type: WELL API Number: 051-06059 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: [MIT last preformed on 7/24/17. Refer to document #401365545](#)

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Gravel	Pass					
Berms	Pass					
		Ditches	Pass			
Ditches	Pass					
		Berms	Pass			
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402475196	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5232251
699801674	Photos for Insp. #699801673	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5232246