

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/11/2020

Submitted Date:

09/14/2020

Document Number:

692402499**FIELD INSPECTION FORM**Loc ID 334789 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoil ndgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211547	WELL	PR	05/01/2001	GW	045-07307	SHAEFFER 18-6	RI
259763	WELL	PR	09/20/2001	GW	045-07781	SHAEFFER 18-6B (F18)	RI
259764	WELL	PR	09/20/2001	GW	045-07782	SHAEFFER 18-6A	RI
259765	WELL	PR	08/24/2001	GW	045-07783	SHAEFFER 18-3A (F18)	RI
259773	WELL	PR	08/24/2001	GW	045-07784	SHAEFFER 18-3B (F18)	RI

General Comment:

This is an Interim Reclamation & Stormwater focused Insp, a follow up to Insp Doc#692402164 Dated 4/29/20. Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

Inspected Facilities				
Facility ID: <u>211547</u>	Type: <u>WELL</u>	API Number: <u>045-07307</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>259763</u>	Type: <u>WELL</u>	API Number: <u>045-07781</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>259764</u>	Type: <u>WELL</u>	API Number: <u>045-07782</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>259765</u>	Type: <u>WELL</u>	API Number: <u>045-07783</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>259773</u>	Type: <u>WELL</u>	API Number: <u>045-07784</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

It appears that Anchors have been removed. CA resolved.

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location was stable and had no sediment migration or erosion concerns at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692402504	Inspection Photos RI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246238