

Inspection Photos

API: 071-08734

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/11/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08734 | Date: 9/11/2020

Inspection Photos



Photo 1. Facing south along the access road ascending the hillside. There is erosion occurring down the road and stormwater is not properly diverted toward the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08734 | Date: 9/11/2020

Inspection Photos



Photo 2. Stormwater is not properly diverted toward the culvert which is causing erosion of the road shown in previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08734 | Date: 9/11/2020

Inspection Photos



Photo 3. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08734 | Date: 9/11/2020