

# Inspection Photos

API: 071-07778

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/11/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07778 | Date: 9/11/2020

## Inspection Photos



**Photo 1.** Facing southwest along the access road ascending the hillside. There is erosion occurring down the road and stormwater is not properly diverted toward the culvert up the road..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07778 | Date: 9/11/2020

## Inspection Photos



**Photo 2.** The culvert along the road has filled in with sediment causing stormwater to flow down the road.



**Photo 3.** Facing back down the road where stormwater is flowing down the road causing the erosion shown in photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07778 | Date: 9/11/2020

## Inspection Photos



**Photo 4.** Another culvert further along the road is partially filled with sediment.



**Photo 5.** There is no culvert outlet protection which is causing erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 6.** Facing west toward the location.

