

# Inspection Photos

API: 071-09485

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/11/2020



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09485 | Date: 9/11/2020

## Inspection Photos



**Photo 1.** Facing southeast along the access road. Stormwater is not properly diverted toward the culvert in this area. Lat/Long:37.14697,-104.88575.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09485 | Date: 9/11/2020



## Inspection Photos



**Photo 2.** Facing northwest toward the location. The electric fence is in disrepair and needs maintenance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09485 | Date: 9/11/2020