

# Inspection Photos

API: 071-07680

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/11/2020



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07680 | Date: 9/11/2020

## Inspection Photos



**Photo 1.** Facing northeast toward the access road. Stormwater is not flowing toward the culvert and is going across the road creating erosion shown in next photo.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07680 | Date: 9/11/2020



## Inspection Photos



**Photo 2.** There is erosion occurring off the fill slope from stormwater flowing across the road shown in previous photo.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07680 | Date: 9/11/2020



## Inspection Photos



**Photo 3.** The culvert is filled in with sediment at beginning of the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07680 | Date: 9/11/2020



## Inspection Photos



**Photo 4.** Facing back down toward the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07680 | Date: 9/11/2020



## Inspection Photos



**Photo 5.** Facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07680 | Date: 9/11/2020