

Location

Overall Good:

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 251213 Type: WELL API Number: 123-19016 Status: PR Insp. Status: WK

Cement

Cement Contractor

Contractor Name: SPN Well Services Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 4226 Cement Volume (sx): 2

Good Return During Job: _____ Cement Type: _____

Comment: [COGCC Inspection Report Summary](#)
 On Monday 9/14/20 at approximately 1245hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Gittlein D 9-7 of Noble Energy at Location ID: 330392 in Weld County, Colorado.
 Weather: Clear Sky
 While there, I witnessed "SPN Well Services" RU Rocky SPN Well Services, RIH with plug. Set CIBP #3 plug @4226' with 2 sacks of cmt on top.
 No violation of the COGCC rules were observed at the time of inspection.
 This is a summary of inspection report.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102377	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246698