

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/11/2020

Submitted Date:

09/14/2020

Document Number:

693200749

FIELD INSPECTION FORM

Loc ID 334387 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Caerus		COGCC.inspections@caerusoilandgas.com	All Piceance inspections
Arauza, Steven		steven.arauza@state.co.us	West Environmental Protection Specialist
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284085	WELL	PR	06/09/2006	GW	045-12081	KEINATH 4-6 (OF4)	SI
477268	SPILL OR RELEASE	CL	06/08/2020		-	OF4 Pad Flowline	EG

General Comment:

[Engineering Integrity Inspection performed on September 11, 2020, to witness pressure test of new installed flowline](#)
[For more information regarding this release, please refer to Supplemental form 19-release report Document #402461447](#)

Inspected Facilities

Facility ID: 284085 Type: WELL API Number: 045-12081 Status: PR Insp. Status: SI

Facility ID: 477268 Type: SPILL OR API Number: - Status: CL Insp. Status: EG

Flowline

#1	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: No Age: New Contents: Multiphase

Integrity Summary

Failures: Internal Corrosion Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Old 3" carbon steel flowlines was abandoned and removed from location
New 2" stainless steel dump flowlines was installed
Flowline passed 4-hour pressure test
Pressure test performed by 3rd party and charted on Crystal Gauge.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200750	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246798