



**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           | adequate |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  | Date: |  |
| Corrective Action: |  |       |  |

**Good Housekeeping:**

|                    |                                       |       |            |
|--------------------|---------------------------------------|-------|------------|
| Type               | UNUSED EQUIPMENT                      |       |            |
| Comment:           | unused electricpanel leaning on fence |       |            |
| Corrective Action: | Comply with Rule 603.f                | Date: | 12/14/2020 |
| Type               | OTHER                                 |       |            |
| Comment:           | Stained soil around WH                |       |            |
| Corrective Action: | Comply with Rule 907.e                | Date: | 12/14/2020 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                       |       |  |
|--------------------|-----------------------|-------|--|
| Type               | PUMP JACK             |       |  |
| Comment:           | fabricated steel pipe |       |  |
| Corrective Action: |                       | Date: |  |
| Type               | WELLHEAD              |       |  |
| Comment:           | chainlink             |       |  |
| Corrective Action: |                       | Date: |  |

**Equipment:**

|                           |  |       |                 |
|---------------------------|--|-------|-----------------|
| Type: Pump Jack           | # 1                                      |       | corrective date |
| Comment:                  |  |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Bradenhead          | # 1                                      |       |                 |
| Comment:                  | appears to be plumbed to surface         |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Ancillary equipment | # 1                                      |       |                 |
| Comment:                  | transformers, meter box & electric panel |       |                 |
| Corrective Action:        |  | Date: |                 |

|                    |                |       |
|--------------------|----------------|-------|
| Type: Prime Mover  | # 1            |       |
| Comment:           | electric motor |       |
| Corrective Action: |                | Date: |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 241406 Type: WELL API Number: 123-09195 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Scout card shows well as PR at the time of inspection well appear to be SI all valves are closed and the electric power is off.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <p><b>COGCC Inspection Report Summary</b><br/>                     On Monday 9/14/2020 at approximately 1520 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Painted Pegasus Petroleum LLC location:</p> <p style="text-align: right;">Oskarson #3 at</p> <p>API #05-123-09195 in Weld County Colorado.<br/>                     While there, I observed a wellsite. Scout card shows well as PR at the time of inspection well appear to be SI all valves are closed and the electric power is off.<br/>                     During this inspection the following possible compliance issues were observed:<br/>                     603.f housekeeping: unused electric panel leaning on fence, CA date 12 14 2020. see photo 4.<br/>                     907.e housekeeping: stained soil around WH, CA date 12-14-2020 see photos 2, 6 &amp; 7. See attached photos.<br/>                     Location is dry, weather is clear.<br/>                     A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.<br/>                     This is a summary of inspection report.</p> | revasr | 09/14/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL   |
|--------------|---------------|---|
| 699302554    | location pics | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246886">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246886</a> |