

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/14/2020

Submitted Date:

09/14/2020

Document Number:

699302549**FIELD INSPECTION FORM**Loc ID 322858 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244377	WELL	PR	06/01/2020	GW	123-12171	OSKARSON E UNIT 1	PR
421981	WELL	PR	05/01/2020	GW	123-33122	OSKARSON 4-4-33	PR
421992	WELL	PR	05/01/2020	GW	123-33124	OSKARSON 4-6-33	PR
422019	WELL	PR	05/01/2020	OW	123-33132	OSKARSON 2-8-33	PR
422027	WELL	PR	05/01/2020	GW	123-33134	OSKARSON 4-8-33	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate x 5		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	chainlink topped with barb wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	chain link topped with barb wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	chain link topped with barb wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Separator	#		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		

Comment:		all appear to be plumbed to surface		Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 3				
Comment:				Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:		card in meter house indicates current calibration		Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 10				
Comment:		automation		Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 5				
Comment:				Date:	
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	
Other (Content)	
Other (Capacity)	235 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:		shares containment with condensate tanks			
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	OTHER	STEEL AST		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	330 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Revas, Robbie

Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

<b>Inspected Facilities</b>				
Facility ID: <u>244377</u>	Type: <u>WELL</u>	API Number: <u>123-12171</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>PR</u>				
Corrective Action:				Date: <u>          </u>
Facility ID: <u>421981</u>	Type: <u>WELL</u>	API Number: <u>123-33122</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>PR</u>				
Corrective Action:				Date: <u>          </u>
Facility ID: <u>421992</u>	Type: <u>WELL</u>	API Number: <u>123-33124</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>PR</u>				
Corrective Action:				Date: <u>          </u>
Facility ID: <u>422019</u>	Type: <u>WELL</u>	API Number: <u>123-33132</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>PR</u>				
Corrective Action:				Date: <u>          </u>
Facility ID: <u>422027</u>	Type: <u>WELL</u>	API Number: <u>123-33134</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>PR</u>				
Corrective Action:				Date: <u>          </u>
<b>COGCC Comments</b>				
Comment  <b>COGCC Inspection Report Summary</b> On Monday 9/14/2020 at approximately 1440 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Crestone Peak Resources location:  <div style="text-align: right; margin-right: 50px;">Oskarson E-1 at</div> Location #322858 in Weld County Colorado. While there, I observed a Multi-well pad and tank battery. During this inspection no compliance issues were observed: See attached photos. Location is dry, weather is clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.		User  revasr	Date  09/14/2020	
<b>Attached Documents</b>				
You can go to COGCC Images ( <a href="https://cogcc.state.co.us/weblink/">https://cogcc.state.co.us/weblink/</a> ) and search by document number:				

Document Num	Description	URL
699302550	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246884">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246884</a>

--