

Inspection Photos
Location Name: AC 18-12V
Location ID: 308030



Photo 1 stormwater issues on access road from Big Bingham main road



Photo 2 stormwater issues on access road from Big Bingham main road

Inspection Photos
Location Name: AC 18-12V
Location ID: 308030



Photo 3 stormwater issues on access road from Big Bingham main road



Photo 4 stormwater issues on access road from Big Bingham main road

Location ID: 308030



Inspection Photos
Location Name: AC 18-12V
Location ID: 308030



Photo 7 stained soil from active leak in separator



Photo 8 Stained soil from active leak in separator.

Inspection Photos
Location Name: AC 18-12V
Location ID: 308030



Photo 9 1" risers not LOTO



Photo 10 Stained soil around liquid ring. Mechanical issues liquid ring leaking fluid.

Inspection Photos
Location Name: AC 18-12V
Location ID: 308030



Photo 11 PU



Photo 12 PU HYD leaking fluid. Stained soil and mechanical issues.

Inspection Photos
Location Name: AC 18-12V
Location ID: 308030



Photo 13 access road stormwater issues sediment being carried down road off location.



Photo 14 Location sign.

Inspection Photos
Location Name: AC 18-12V
Location ID: 308030



Photo 15 Approx.. 3in of what appears to be non E&P waste
in 30bbl produced water tank.