

Inspection Photos
Operator: BP America
API: 067-06482
Date: 9/11/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with grasses and shrubs such as western wheatgrass and rubber rabbitbrush.



Photo 3. View of the western project area from the northwestern corner facing southward. Cobble run-down placed in erosional channel appears to be functioning. Note that smooth cobble can accelerate velocity of water flows and is not recommended as a stormwater BMP. Continue monitoring to ensure site stabilization.



Photo 4. View of reference area vegetation comprised of gambel oak shrubland with a mix of grasses, shrubs, and forbs in the understory, such as western wheatgrass, *Heterotheca villosa*, and rubber rabbitbrush.